

#### Lake Whatcom Water and Sewer District

Sudden Valley WTP Assessment Project

June 29, 2021

Project Team: Russ Porter P.E., Keith Stewart P.E.



#### **Presentation Outline**

- Project Description & Purpose
- Project History
- Alternatives Analysis Summary
- Risk Assessment Summary
- WTP Alternatives Analysis Report
- Next Steps





## Project Description & Purpose

- South Shore Water System Assessment
  - Assess conditions at Sudden Valley WTP
  - Provide basis for decision making with regards to WTP modifications and / or continued use
    - Phase I
      - Assess existing condition of structures and equipment
    - Phase II
      - Provide alternatives analysis & recommendations





#### **Project History**

- Phase I WTP Condition Assessment
  - Assessed existing buildings and process in February 2020
    - Process, Electrical, Structural, HVAC











# **Project History**

#### • Phase I - WTP Condition Assessment

- Assessed existing buildings and process in February 2020
  - Process, Electrical, Structural, HVAC
- Assessment Report completed in July 2020
- Identified both high and low priority improvements
  - Structures were in good condition
  - Treatment is effective, but some components showing signs of age and use
  - Lack of available space
  - Anchoring and supports need seismic upgrades
  - Minor to moderate corrosion and/or deterioration
  - Some lack of redundancy puts WTP at risk





#### TABLE 3-1

#### Sudden Valley WTP High Priority Modifications Summary

Modification	Location <sup>(1)</sup>	Discipline <sup>(2)</sup>
Conduct chlorine disinfection system alternatives analysis	MB	Р
Chlorine gas system modifications	MB	Р
Alum storage and metering pump system modifications	MB	Р
Soda Ash storage and metering pump system modifications	MB	Р
Conduct backwash system alternatives analysis	MB	Р
Replace existing clearwell and CCB level switches	MB	Р
Replace corroded steel supports	MB	S
Prepare and coat steel tanks (Floc, Soda Ash, and Filters 1/2)	MB	S
Install seismic bracing for electrical conduit, electrical equipment, and	MB/FDB	ç
treatment equipment	MD/ITD	5
Complete detailed structural evaluation	MB/FPB	S
Relocate existing laboratory electrical equipment	MB	Α
Remove soil cover, vegetation growth, and organic debris from	MB	٨
building exterior and roof	MB A	
Provide water upgrades to safety shower and eyewash	MB	Α
Add fire and smoke alarm system	MB/FPB	Α
Investigate current heating schedule	MB/FPB	Μ
Combine all existing plant records into a single as-built planset	MB/FPB	E
Complete a comprehensive electrical system audit	MB/FPB	E
Remove chemicals and metering equipment away from MCCs	MB	E
Review historical peak demand electrical consumption	MB/FPB	E
Replace MCC1 and MCC2 with new, current technology	MB/FPB	E
Replace MCC3 to address panel and interior component corrosion	MB	E



 MB = WTP Main Building. FPB = Finished Water Pump Building. CCB = Chlorine Contact Basin.



(2) P = Process, S = Structural, A = Architectural, M = Mechanical, and E = Electrical.

TA	BL	E	3	-2

#### Sudden Valley WTP Recommended Modifications Summary

Modify/repair existing flocculation tank         MB         P           Provide new grout floor within raw water pump pit         MB         P           Drain and clean the clearwell         MB         P           Procure spare backwash flow meter         MB         P           Procure dedicated confined space equipment for the WTP         MB         P           Install additional access ladder to Filters 1 and 2 and Filters 3 and 4         MB         P           Revise C1 calculations to include clearwell and BE of 0.1         MB         P           Revise piping and conduit above flocculation tank         MB         P           Provide additional Operator In Trouble alarming equipment         MB/FPB         P           Replace existing pressure gauges         FPB         P           Procure a spare finished water pump motor         FPB         P           Complete a performance test of the raw water, transfer, and finished water pumps         MB         P           Prepare and coat exposed ceiling rebar         MB         A         A           Address deficiencies found in 2016 seismic report         CCCB         S           Address deficiencies found in setroom         MB         A           Investigate additional site security measures         MB         A           Repair seepage/leak	Modification	Location <sup>(1)</sup>	Discipline <sup>(2)</sup>
Provide new grout floor within raw water pump pitMBPDrain and clean the clearwellMBPProcure spare backwash flow meterMBPProcure dedicated confined space equipment for the WTPMBPInstall additional access ladder to Filters 1 and 2 and Filters 3 and 4MBPRevise CT calculations to include clearwell and BE of 0.1MBPRevise piping and conduit above flocculation tankMBPProvide additional Operator In Trouble alarming equipmentMB/FPBPReplacing existing tube-style level alarm at flocculation tankMBPProcure a spare finished water pump motorFPBPReplace existing pressure gaugesFPBPImprove the visibility of the existing clearwell hatchMBPComplete a performance test of the raw water, transfer, and finished water pumpsMB/FPBPPrepare and coat exposed ceiling rebarMBSAddress deficiencies found in 2016 seismic reportCCBSAddress deteriorating conditions in restroomMBAInvestigate additional site security measuresMB/FPBARepair seepage/leaks at storefront window assembliesMBARevise existing storefortFPBARevise existing storefort window to provide larger door openingMBAAARepair seepage/leaks at storefront window assembliesMBAARepair rack in generator existing generatorFPBRepair rack in generator existing	Modify/repair existing flocculation tank	MB	Р
Drain and clean the clearwellMBPProcure spare backwash flow meterMBPProcure dedicated confined space equipment for the WTPMBPInstall additional access ladder to Filters 1 and 2 and Filters 3 and 4MBPRevise CT calculations to include clearwell and BE of 0.1MBPRevise piping and conduit above flocculation tankMBPProvide additional Operator In Trouble alarming equipmentMB/FPBPReplacing existing tube-style level alarm at flocculation tankMBPProcure a spare finished water pump motorFPBPReplace existing pressure gaugesFPBPImprove the visibility of the existing clearwell hatchMBPComplete a performance test of the raw water, transfer, and finished water pumpsPPPrepare and coat exposed ceiling rebarMBSAddress deficiencies found in 2016 seismic reportCCBSAddress deteriorating conditions in restroomMBAInvestigate additional site security measuresMB/FPBARepair wall seepage above MCC3MBARepair wall seepage above MCC3MBARevise existing floor to promote drainage to existing greenatorMBARevise existing floor to promote drainage to existing greenatorFPBMRepair crack in generator exhaust pipingFPBMConduct energy and heat auditMB/FPBERepair wall seepage loove MCC3MBARepair wall seepage lock systems<	Provide new grout floor within raw water pump pit	MB	Р
Procure spare backwash flow meterMBPProcure dedicated confined space equipment for the WTPMBPInstall additional access ladder to Filters 1 and 2 and Filters 3 and 4MBPRevise CT calculations to include clearwell and BE of 0.1MBPRevise piping and conduit above flocculation tankMBPProvide additional Operator In Trouble alarming equipmentMB/FPBPReplace existing tube-style level alarm at flocculation tankMBPProcure a spare finished water pump motorFPBPReplace existing pressure gaugesFPBPImprove the visibility of the existing clearwell hatchMBPComplete a performance test of the raw water, transfer, and finished water pumpsMB/FPBPPrepare and coat exposed ceiling rebarMBSAddress deficiencies found in 2016 seismic reportCCBSPerform formal CCB coating inspectionCCBSAddress deteriorating conditions in restroomMBAInvestigate additional site security measuresMB/FPBARepair wall seepage above MCC3MBARevise existing storefront window assembliesMBAModify floor to promote drainage to existing trench drainMBAConduct energy and heat auditMB/FPBMConduct energy and heat auditMB/FPBMConduct energy and heat auditMB/FPBEConduct energy and heat auditMB/FPBEConduct energy and heat auditMB/FPB	Drain and clean the clearwell	MB	Р
Procure dedicated confined space equipment for the WTPMBPInstall additional access ladder to Filters 1 and 2 and Filters 3 and 4MBPRevise CT calculations to include clearwell and BE of 0.1MBPRevise piping and conduit above flocculation tankMBPProvide additional Operator In Trouble alarming equipmentMB/FPBPReplacing existing tube-style level alarm at flocculation tankMBPProcure a spare finished water pump motorFPBPReplace existing pressure gaugesFPBPImprove the visibility of the existing clearwell hatchMBPComplete a performance test of the raw water, transfer, and finished water pumpsMB/FPBPPrepare and coat exposed ceiling rebarMBSAddress deficiencies found in 2016 seismic reportCCBSPerform formal CCB coating inspectionCCBSAddress deteriorating conditions in restroomMBAInvestigate additional site security measuresMB/FPBARepair seepage/leaks at storefront window assembliesMBARevise existing storefront window assembliesMBARevise existing for existing generatorFPBMConduct energy and heat auditMB/FPBMConduct energy and heat auditMBARepair seepage/leaks at storefront window assembliesMBARepair seepage/leaks at storefront window assembliesMBARevise existing fluorescent light fixtures with LED equipmentMB/FPB	Procure spare backwash flow meter	MB	Р
Install additional access ladder to Filters 1 and 2 and Filters 3 and 4MBPRevise CT calculations to include clearwell and BE of 0.1MBPRevise piping and conduit above flocculation tankMBPProvide additional Operator In Trouble alaming equipmentMB/FPBPReplacing existing tube-style level alarm at flocculation tankMBPProcure a spare finished water pump motorFPBPReplace existing pressure gaugesFPBPComplete a performance test of the raw water, transfer, and finished water pumpsMB/FPBPPrepare and coat exposed ceiling rebarMBSAddress deficiencies found in 2016 seismic reportCCBSAddress deficiencies found in 2016 seismic reportCCBSAddress deficiencies found in 2016 seismic reportCCBSAddress deteriorating conditions in restroomMBAInvestigate additional site security measuresMB/FPBARepair wall seepage above MCC3MBARevise existing storefront window assembliesMBAModify floor to promote drainage to existing trench drainMBARevise existing floorescent light fixtures with LED equipmentMB/FPBERevise existing floorescent light fixtures with LED equipmentMB/FPBERepair cack in generator exhaust pipingFPBEConduct energy and heat auditMB/FPBEERepair cack in generator exhaust pipingFPBEConduct energy and heat auditMB/FPB<	Procure dedicated confined space equipment for the WTP	MB	Р
Revise CT calculations to include clearwell and BE of 0.1MBPRevise piping and conduit above flocculation tankMBPProvide additional Operator In Trouble alarming equipmentMB/FPBPReplacing existing tube-style level alarm at flocculation tankMBPProcure a spare finished water pump motorFPBPReplace existing pressure gaugesFPBPImprove the visibility of the existing clearwell hatchMBPComplete a performance test of the raw water, transfer, and finished water pumpsMB/FPBPPrepare and coat exposed ceiling rebarMBSAddress deficiencies found in 2016 seismic reportCCBSPerform formal CCB coating inspectionCCBSAddress deteriorating conditions in restroomMBAInvestigate additional site security measuresMB/FPBARepair wall seepage/leaks at storefront window assembliesMBAModify floor to promote drainage to existing trench drainMBARevise existing storefront window to provide larger door openingMBARepair eack in generator exhaust pipingFPBMConduct annual load testing for existing generatorFPBEReplace existing fluorescent light fixtures with LED equipmentMB/FPBEReplace existing fluorescent light fixtures with LED equipmentMB/FPBEReplace existing fluorescent light fixtures with LED equipmentMB/FPBEReplace existing fluorescent light fixtures with LED equipmentMB/FPB </td <td>Install additional access ladder to Filters 1 and 2 and Filters 3 and 4</td> <td>MB</td> <td>Р</td>	Install additional access ladder to Filters 1 and 2 and Filters 3 and 4	MB	Р
Revise piping and conduit above flocculation tankMBPProvide additional Operator In Trouble alarming equipmentMB/FPBPReplacing existing tube-style level alarm at flocculation tankMBPProcure a spare finished water pump motorFPBPReplace existing pressure gaugesFPBPImprove the visibility of the existing clearwell hatchMBPComplete a performance test of the raw water, transfer, and finished water pumpsMB/FPBPPrepare and coat exposed ceiling rebarMBSAddress deficiencies found in 2016 seismic reportCCBSPerform formal CCB coating inspectionCCBSAddress deteriorating conditions in restroomMBAInvestigate additional site security measuresMB/FPBARepair sepage/leaks at storefront window assembliesMBARevise existing storefront window to provide larger door openingMBARevise existing storefront window to provide larger door openingMBARepair crack in generator exhaust pipingFPBMConduct energy and heat auditMB/FPBMRepair crack in generator exhaust pipingFPBMConduct annual load testing for existing generatorFPBEReplace AC backed system with DC backed systemsMB/FPBEReplace devisiting electrical panelboardsMB/FPBEReport crack in generator exhaust pipingFPBEReplace AC backed system with DC backed systemsMB/FPBE	Revise CT calculations to include clearwell and BE of 0.1	MB	Р
Provide additional Operator In Trouble alarming equipmentMB/FPBPReplacing existing tube-style level alarm at flocculation tankMBPProcure a spare finished water pump motorFPBPReplace existing pressure gaugesFPBPImprove the visibility of the existing clearwell hatchMBPComplete a performance test of the raw water, transfer, and finished water pumpsMB/FPBPPrepare and coat exposed ceiling rebarMBSAddress deficiencies found in 2016 seismic reportCCBSPerform formal CCB coating inspectionCCBSAddress deteriorating conditions in restroomMBAInvestigate additional site security measuresMB/FPBARepair wall seepage above MCC3MBARepair seepage/leaks at storefront window assembliesMBAModify floor to promote drainage to existing trench drainMBARelocate stored filter media and other supplies equipmentMBARepair crack in generator exhaust pipingFPBMConduct energy and heat auditMB/FPBMRepaire crack in generator existing generatorFPBEReplace tisting fluorescent light fixtures with LED equipmentMB/FPBEReplace actisting fluorescent light fixtures with LED equipmentMB/FPBEReplace acting deletrical panelboardsMB/FPBEReplace actisting electrical conduitMB/FPBEReplace actisting electrical conduitMBFRepaire e	Revise piping and conduit above flocculation tank	MB	Р
Replacing existing tube-style level alarm at flocculation tankMBPProcure a spare finished water pump motorFPBPReplace existing pressure gaugesFPBPImprove the visibility of the existing clearwell hatchMBPComplete a performance test of the raw water, transfer, and finished water pumpsMB/FPBPPrepare and coat exposed ceiling rebarMBSAddress deficiencies found in 2016 seismic reportCCBSPerform formal CCB coating inspectionCCBSAddress deteriorating conditions in restroomMBAInvestigate additional site security measuresMB/FPBARepair wall seepage above MCC3MBARepair seepage/leaks at storefront window assembliesMBAModify floor to promote drainage to existing trench drainMBARevise existing storefront window to provide larger door openingMBARepair crack in generator exhaust pipingFPBMConduct energy and heat auditMB/FPBMConduct annual load testing for existing generatorFPBEReplace existing fluorescent light fixtures with LED equipmentMB/FPBEReplace AC backed system with DC backed systemsMB/FPBERepute floor mounted electrical conduitMB/FPBERepute acting storeford in generatorFPBEReplace acting floor spectral panelboardsMB/FPBEReplace acting floor spectral panelboardsMB/FPBEReplace AC backed sy	Provide additional Operator In Trouble alarming equipment	MB/FPB	Р
Procure a spare finished water pump motorFPBPReplace existing pressure gaugesFPBPImprove the visibility of the existing clearwell hatchMBPComplete a performance test of the raw water, transfer, and finished water pumpsMB/FPBPPrepare and coat exposed ceiling rebarMBSAddress deficiencies found in 2016 seismic reportCCBSPerform formal CCB coating inspectionCCBSAddress deteriorating conditions in restroomMBAInvestigate additional site security measuresMB/FPBARepair well seepage above MCC3MBARepair seepage/leaks at storefront window assembliesMBAModify floor to promote drainage to existing trench drainMBARelocate stored filter media and other supplies equipmentMBAConduct energy and heat auditMB/FPBMRepair crack in generator exhaust pipingFPBMConduct annual load testing for existing generatorFPBEReplace AC backed system with DC backed systemsMB/FPBERenoute field wiring within grey/blue wall mounted panelsMBEModify transfer pump and based on long-term operations strategyMBE	Replacing existing tube-style level alarm at flocculation tank	MB	Р
Replace existing pressure gaugesFPBPImprove the visibility of the existing clearwell hatchMBPComplete a performance test of the raw water, transfer, and finished water pumpsMB/FPBPPrepare and coat exposed ceiling rebarMBSAddress deficiencies found in 2016 seismic reportCCBSPerform formal CCB coating inspectionCCBSAddress deteriorating conditions in restroomMBAInvestigate additional site security measuresMB/FPBARemove heavy organic debris from roofFPBARepair wall seepage above MCC3MBARepair seepage/leaks at storefront window assembliesMBAModify floor to promote drainage to existing trench drainMBARelocate stored filter media and other supplies equipmentMBAConduct energy and heat auditMB/FPBMRepair crack in generator exhaust pipingFPBMConduct annual load testing for existing generatorFPBEReplace existing fluorescent light fixtures with LED equipmentMB/FPBEReplace AC backed system with DC backed systemsMB/FPBEConsolidate existing electrical panelboardsMB/FPBEReroute floor mounted electrical conduitMB/FPBEReroute field wiring within grey/blue wall mounted panelsMBEModify transfer pump pad based on long-term operations strategyMBE	Procure a spare finished water pump motor	FPB	Р
Improve the visibility of the existing clearwell hatchMBPComplete a performance test of the raw water, transfer, and finished water pumpsMB/FPBPPrepare and coat exposed ceiling rebarMBSAddress deficiencies found in 2016 seismic reportCCBSPerform formal CCB coating inspectionCCBSAddress deteriorating conditions in restroomMBAInvestigate additional site security measuresMB/FPBARemove heavy organic debris from roofFPBARepair wall seepage above MCC3MBAModify floor to promote drainage to existing trench drainMBARelocate stored filter media and other supplies equipmentMBAConduct energy and heat auditMB/FPBMRepair crack in generator exhaust pipingFPBMConduct annual load testing for existing generatorFPBEReplace existing fluorescent light fixtures with LED equipmentMB/FPBEReplace AC backed system with DC backed systemsMB/FPBEConsolidate existing electrical panelboardsMB/FPBEReroute floor mounted electrical conduitMB/FPBEReroute field wiring within grey/blue wall mounted panelsMBEModify transfer pump pad based on long-term operations strategyMBE	Replace existing pressure gauges	FPB	Р
Complete a performance test of the raw water, transfer, and finished water pumpsMB/FPBPPrepare and coat exposed ceiling rebarMBSAddress deficiencies found in 2016 seismic reportCCBSPerform formal CCB coating inspectionCCBSAddress deteriorating conditions in restroomMBAInvestigate additional site security measuresMB/FPBARemove heavy organic debris from roofFPBARepair wall seepage above MCC3MBARepair seepage/leaks at storefront window assembliesMBAModify floor to promote drainage to existing trench drainMBARevise existing storefront window to provide larger door openingMBARelocate stored filter media and other supplies equipmentMBAConduct annual load testing for existing generatorFPBMConduct annual load testing for existing generatorFPBEReplace existing fluorescent light fixtures with LED equipmentMB/FPBEReplace AC backed system with DC backed systemsMB/FPBEConsolidate existing electrical panelboardsMBEReroute field wiring within grey/blue wall mounted panelsMBEModify transfer pump pad based on long-term operations strategyMBE	Improve the visibility of the existing clearwell hatch	MB	Р
Prepare and coat exposed ceiling rebarMBSAddress deficiencies found in 2016 seismic reportCCBSPerform formal CCB coating inspectionCCBSAddress deteriorating conditions in restroomMBAInvestigate additional site security measuresMB/FPBARemove heavy organic debris from roofFPBARepair wall seepage above MCC3MBARepair seepage/leaks at storefront window assembliesMBAModify floor to promote drainage to existing trench drainMBARevise existing storefront window to provide larger door openingMBARelocate stored filter media and other supplies equipmentMBAConduct energy and heat auditMB/FPBMRepair crack in generator exhaust pipingFPBMConduct annual load testing for existing generatorFPBEReplace AC backed system with DC backed systemsMB/FPBEReroute floor mounted electrical panelboardsMB/FPBEReroute field wiring within grey/blue wall mounted panelsMBEModify transfer pump pad based on long-term operations strategyMBEFuel tank relocation investigationFPBE	Complete a performance test of the raw water, transfer, and finished water pumps	MB/FPB	Р
Address deficiencies found in 2016 seismic reportCCBSPerform formal CCB coating inspectionCCBSAddress deteriorating conditions in restroomMBAInvestigate additional site security measuresMB/FPBARemove heavy organic debris from roofFPBARepair wall seepage above MCC3MBARepair seepage/leaks at storefront window assembliesMBAModify floor to promote drainage to existing trench drainMBARevise existing storefront window to provide larger door openingMBARelocate stored filter media and other supplies equipmentMBAConduct energy and heat auditMB/FPBMConduct annual load testing for existing generatorFPBEReplace AC backed system with DC backed systemsMB/FPBEReroute floor mounted electrical panelboardsMB/FPBEReroute field wiring within grey/blue wall mounted panelsMBEModify transfer pump pad based on long-term operations strategyMBEFuel tank relocation investigationFPBE	Prepare and coat exposed ceiling rebar	MB	S
Perform formal CCB coating inspectionCCBSAddress deteriorating conditions in restroomMBAInvestigate additional site security measuresMB/FPBARemove heavy organic debris from roofFPBARepair wall seepage above MCC3MBARepair seepage/leaks at storefront window assembliesMBAModify floor to promote drainage to existing trench drainMBARevise existing storefront window to provide larger door openingMBARelocate stored filter media and other supplies equipmentMBAConduct energy and heat auditMB/FPBMRepair crack in generator exhaust pipingFPBMConduct annual load testing for existing generatorFPBEReplace AC backed system with DC backed systemsMB/FPBEConsolidate existing electrical panelboardsMBFReroute floor mounted electrical conduitMBFMBFFFReroute field wiring within grey/blue wall mounted panelsMBEModify transfer pump pad based on long-term operations strategyMBEFuel tank relocation investigationFPBE	Address deficiencies found in 2016 seismic report	CCB	S
Address deteriorating conditions in restroomMBAInvestigate additional site security measuresMB/FPBARemove heavy organic debris from roofFPBARepair wall seepage above MCC3MBARepair seepage/leaks at storefront window assembliesMBAModify floor to promote drainage to existing trench drainMBARevise existing storefront window to provide larger door openingMBARelocate stored filter media and other supplies equipmentMBAConduct energy and heat auditMB/FPBMRepair crack in generator exhaust pipingFPBMConduct annual load testing for existing generatorFPBEReplace AC backed system with DC backed systemsMB/FPBEConsolidate existing electrical panelboardsMB/FPBEReroute floor mounted electrical conduitMB/FPBEReroute field wiring within grey/blue wall mounted panelsMBEModify transfer pump pad based on long-term operations strategyMBEFuel tank relocation investigationFPBE	Perform formal CCB coating inspection	CCB	S
Investigate additional site security measuresMB/FPBARemove heavy organic debris from roofFPBARepair wall seepage above MCC3MBARepair seepage/leaks at storefront window assembliesMBAModify floor to promote drainage to existing trench drainMBARevise existing storefront window to provide larger door openingMBARelocate stored filter media and other supplies equipmentMBAConduct energy and heat auditMB/FPBMRepair crack in generator exhaust pipingFPBMConduct annual load testing for existing generatorFPBEReplace existing fluorescent light fixtures with LED equipmentMB/FPBEReplace AC backed system with DC backed systemsMB/FPBEConsolidate existing electrical panelboardsMB/FPBEReroute floor mounted electrical conduitMB/FPBEReroute field wiring within grey/blue wall mounted panelsMBEModify transfer pump pad based on long-term operations strategyMBEFuel tank relocation investigationFPBE	Address deteriorating conditions in restroom	MB	Α
Remove heavy organic debris from roofFPBARepair wall seepage above MCC3MBARepair seepage/leaks at storefront window assembliesMBAModify floor to promote drainage to existing trench drainMBARevise existing storefront window to provide larger door openingMBARelocate stored filter media and other supplies equipmentMBAConduct energy and heat auditMB/FPBMRepair crack in generator exhaust pipingFPBMConduct annual load testing for existing generatorFPBEReplace existing fluorescent light fixtures with LED equipmentMB/FPBEReplace AC backed system with DC backed systemsMB/FPBEConsolidate existing electrical panelboardsMB/FPBEReroute floor mounted electrical conduitMB/FPBEReroute field wiring within grey/blue wall mounted panelsMBEModify transfer pump pad based on long-term operations strategyMBEFuel tank relocation investigationFPBE	Investigate additional site security measures	MB/FPB	Α
Repair wall seepage above MCC3MBARepair seepage/leaks at storefront window assembliesMBAModify floor to promote drainage to existing trench drainMBARevise existing storefront window to provide larger door openingMBARelocate stored filter media and other supplies equipmentMBAConduct energy and heat auditMB/FPBMRepair crack in generator exhaust pipingFPBMConduct annual load testing for existing generatorFPBEReplace existing fluorescent light fixtures with LED equipmentMB/FPBEReplace AC backed system with DC backed systemsMB/FPBEConsolidate existing electrical panelboardsMB/FPBEReroute floor mounted electrical conduitMB/FPBEReroute field wiring within grey/blue wall mounted panelsMBEModify transfer pump pad based on long-term operations strategyMBEFuel tank relocation investigationFPBE	Remove heavy organic debris from roof	FPB	A
Repair seepage/leaks at storefront window assembliesMBAModify floor to promote drainage to existing trench drainMBARevise existing storefront window to provide larger door openingMBARelocate stored filter media and other supplies equipmentMBAConduct energy and heat auditMB/FPBMRepair crack in generator exhaust pipingFPBMConduct annual load testing for existing generatorFPBEReplace existing fluorescent light fixtures with LED equipmentMB/FPBEReplace AC backed system with DC backed systemsMB/FPBEConsolidate existing electrical panelboardsMB/FPBEReroute field wiring within grey/blue wall mounted panelsMBEModify transfer pump pad based on long-term operations strategyMBEFuel tank relocation investigationFPBE	Repair wall seepage above MCC3	MB	Α
Modify floor to promote drainage to existing trench drainMBARevise existing storefront window to provide larger door openingMBARelocate stored filter media and other supplies equipmentMBAConduct energy and heat auditMB/FPBMRepair crack in generator exhaust pipingFPBMConduct annual load testing for existing generatorFPBEReplace existing fluorescent light fixtures with LED equipmentMB/FPBEReplace AC backed system with DC backed systemsMB/FPBEConsolidate existing electrical panelboardsMB/FPBEReroute floor mounted electrical conduitMB/FPBEReroute field wiring within grey/blue wall mounted panelsMBEModify transfer pump pad based on long-term operations strategyMBEFuel tank relocation investigationFPBE	Repair seepage/leaks at storefront window assemblies	MB	A
Revise existing storefront window to provide larger door openingMBARelocate stored filter media and other supplies equipmentMBAConduct energy and heat auditMB/FPBMRepair crack in generator exhaust pipingFPBMConduct annual load testing for existing generatorFPBEReplace existing fluorescent light fixtures with LED equipmentMB/FPBEReplace AC backed system with DC backed systemsMB/FPBEConsolidate existing electrical panelboardsMB/FPBEReroute floor mounted electrical conduitMB/FPBEReroute field wiring within grey/blue wall mounted panelsMBEModify transfer pump pad based on long-term operations strategyMBEFuel tank relocation investigationFPBE	Modify floor to promote drainage to existing trench drain	MB	Α
Relocate stored filter media and other supplies equipmentMBAConduct energy and heat auditMB/FPBMRepair crack in generator exhaust pipingFPBMConduct annual load testing for existing generatorFPBEReplace existing fluorescent light fixtures with LED equipmentMB/FPBEReplace AC backed system with DC backed systemsMB/FPBEConsolidate existing electrical panelboardsMB/FPBEReroute floor mounted electrical conduitMB/FPBEReroute field wiring within grey/blue wall mounted panelsMBEModify transfer pump pad based on long-term operations strategyMBEFuel tank relocation investigationFPBE	Revise existing storefront window to provide larger door opening	MB	A
Conduct energy and heat auditMB/FPBMRepair crack in generator exhaust pipingFPBMConduct annual load testing for existing generatorFPBEReplace existing fluorescent light fixtures with LED equipmentMB/FPBEReplace AC backed system with DC backed systemsMB/FPBEConsolidate existing electrical panelboardsMB/FPBEReroute floor mounted electrical conduitMB/FPBEReroute field wiring within grey/blue wall mounted panelsMBEModify transfer pump pad based on long-term operations strategyMBEFuel tank relocation investigationFPBE	Relocate stored filter media and other supplies equipment	MB	A
Repair crack in generator exhaust pipingFPBMConduct annual load testing for existing generatorFPBEReplace existing fluorescent light fixtures with LED equipmentMB/FPBEReplace AC backed system with DC backed systemsMB/FPBEConsolidate existing electrical panelboardsMB/FPBEReroute floor mounted electrical conduitMB/FPBEReroute field wiring within grey/blue wall mounted panelsMBEModify transfer pump pad based on long-term operations strategyMBEFuel tank relocation investigationFPBE	Conduct energy and heat audit	MB/FPB	Μ
Conduct annual load testing for existing generatorFPBEReplace existing fluorescent light fixtures with LED equipmentMB/FPBEReplace AC backed system with DC backed systemsMB/FPBEConsolidate existing electrical panelboardsMB/FPBEReroute floor mounted electrical conduitMB/FPBEReroute field wiring within grey/blue wall mounted panelsMBEModify transfer pump pad based on long-term operations strategyMBEFuel tank relocation investigationFPBE	Repair crack in generator exhaust piping	FPB	М
Replace existing fluorescent light fixtures with LED equipmentMB/FPBEReplace AC backed system with DC backed systemsMB/FPBEConsolidate existing electrical panelboardsMB/FPBEReroute floor mounted electrical conduitMB/FPBEReroute field wiring within grey/blue wall mounted panelsMBEModify transfer pump pad based on long-term operations strategyMBEFuel tank relocation investigationFPBE	Conduct annual load testing for existing generator	FPB	E
Replace AC backed system with DC backed systemsMB/FPBEConsolidate existing electrical panelboardsMB/FPBEReroute floor mounted electrical conduitMB/FPBEReroute field wiring within grey/blue wall mounted panelsMBEModify transfer pump pad based on long-term operations strategyMBEFuel tank relocation investigationFPBE	Replace existing fluorescent light fixtures with LED equipment	MB/FPB	E
Consolidate existing electrical panelboardsMB/FPBEReroute floor mounted electrical conduitMB/FPBEReroute field wiring within grey/blue wall mounted panelsMBEModify transfer pump pad based on long-term operations strategyMBEFuel tank relocation investigationFPBE	Replace AC backed system with DC backed systems	MB/FPB	E
Reroute floor mounted electrical conduit     MB/FPB     E       Reroute field wiring within grey/blue wall mounted panels     MB     E       Modify transfer pump pad based on long-term operations strategy     MB     E       Fuel tank relocation investigation     FPB     E	Consolidate existing electrical panelboards	MB/FPB	E
Reroute field wiring within grey/blue wall mounted panelsMBEModify transfer pump pad based on long-term operations strategyMBEFuel tank relocation investigationFPBE	Reroute floor mounted electrical conduit	MB/FPB	E
Modify transfer pump pad based on long-term operations strategyMBEFuel tank relocation investigationFPBE	Reroute field wiring within grey/blue wall mounted panels	MB	E
Fuel tank relocation investigation FPB E	Modify transfer pump pad based on long-term operations strategy	MB	E
	Fuel tank relocation investigation	FPB	E





 MB = WTP Main Building. FPB = Finished Water Pump Building. CCB = Chlorine Contact Basin.

(2) P = Process, S = Structural, A = Architectural, M = Mechanical, and E = Electrical.

# **Project History**

- Phase II WTP Alternatives Analysis
  - Incorporate Assessment recommendations and analyze various treatment alternatives
  - A la carte approach
    - Pumping, seismic, structural, and coatings
    - Chemical, disinfection, filtration, and backwash
  - Board presentations for involvement/education
  - Final Alternatives Analysis Report
    - Assessment Report
    - Board & Staff input
    - Financial Analysis information
    - Recommendations for District implementation





### Project Goals

#### Phase II - Alternatives Analysis

- G1 Maintain exceptional WQ performance record
- G2 Accommodate immediate need for additional space and separation of chemicals/electrical equipment
- G3 Provide adequate equipment and process redundancy
- G4 Improve access and flexibility for equipment repair/rehabilitation and/or future expansion
- G5 Provide capacity for full buildout flow (1,400 gpm)
- G6 Provide treatment equipment for 30 or 50-year time period





- Pump Performance TM1
  - Pump flow and pressure testing
    - Finished water Pumps
      - Performing at or near design curve
      - Lack of optimized control (VFDs)
      - Associated electrical components outdated
    - Transfer Pumps
      - Testing not completed due to component restrictions
      - Lack of optimized control (VFDs)
      - Associated electrical components outdated
    - Raw Water Pumps
      - Testing not completed due to component restrictions
      - Associated electrical components outdated and corroded
    - Recommendations
      - Plan for replacement of FWP and TP. Replace RWPs





- Pump Performance TM1
  - Pump flow and pressure testing



**Raw Water Pumps** – Raw Water Pump 2 is original (1972) and near the end of its recommended useful life.



**Transfer Pumps** – Pumps are original (1992) and near the end of their recommended useful life.



**Finished Water Pumps** – Pumps are original (1992) and near the end of their recommended useful life.



- Chlorine Contact Basin Coatings TM2
  - Interior and Exterior Coating Assessment
    - Exterior sidewall coating in fair condition
      - Recommend replacement within 5-10 years
    - Exterior roof coating in moderate/poor condition
      - Recommend replacement within 5 years
    - Interior coating in fair condition
      - Recommend replacement within 5-10 years
    - Recommendations
      - Seal welding, additional roof hatch, exterior ladder security, additional access security measures
      - New exterior and interior coating systems (<7 years)





Chlorine Contact Basin Coatings – TM2
 Interior and Exterior Coating Assessment



**CCB** – Tank was erected in 1992.



**Corrosion** – Tank has several corrosion spots, some of which have been repaired.



**Algae** – Roof exhibits lichen and algae growth, both of which may have damaged the coatings.





- Seismic Analysis– TM3
  - Complete Tier 2/Tier 3 Seismic analysis
    - Main Building
      - No structural deficiencies identified
      - Non-structural deficiencies include additional bracing
    - Finished Water Pump Building
      - Shear wall and diaphragm shear structural deficiencies
      - Non-structural deficiencies include additional bracing and securing existing gas piping
    - Chlorine Contact Basin (CCB)
      - Foundation ring wall deficiencies identified (BHC, 2016)
      - Nonstructural deficiencies include flexible piping connections





• Seismic Analysis– TM3

Complete Tier 2/Tier 3 Seismic analysis



Example of piping with

insufficient seismic support



**Seismic support** – Example of equipment with insufficient seismic support



**Seismic Support** – Conduit within the FWP Building with insufficient seismic bracing.



- Chemical System TM4
  - Alum (coagulant) & Soda Ash (pH control) system
    - Alum
      - Best coagulant for District use
      - Tank is beyond useful life, metering pump lacks redundancy and controls, tank filling is cumbersome, tank location restricts other WTP uses
    - Soda Ash
      - Best pH control for District use
      - Tank in fair condition, mixers in poor condition, access is restricted and requires significant manual labor for addition, chemical storage in building
      - Tank location restricts other WTP uses and likely contributes to corrosion of piping and other equipment
  - Recommendations
    - Replace alum tank, both metering pump systems, soda ash mixers
    - Relocate components to new chemical room/building to provide separation and reduced labor





- Chemical System– TM4
  - Alum (coagulant) & Soda Ash (pH control) system



**Alum Storage Tank** – HPDE. Installed in 1992 and beyond its recommended useful life (15-17 years).



**Soda Ash Storage Tank & Platform** – Welded steel. Installed in 1992 and in good condition. Platform in fair condition while the mixer is in poor condition



**Metering Pumps** – Lack of features requires daily manual calibration.





#### • Filtration System- TM5

- Filtration Alternatives
  - Status Quo
    - Rehabilitate all components for continued use in existing bldg.
  - Modified use of existing filters
    - New pretreatment, filter rehabilitation,
    - Requires new building
  - New rapid rate mixed media filter units
    - New filters with pretreatment
    - Requires new building
  - New membrane treatment filter units
    - New treatment and filtration
    - Requires new building





- Filtration System– TM5
  - Filtration Alternatives



\* Typical package filtration equipment with contact adsorption clarifier (CAC).



\* Typical membrane filtration equipment



**DAF** – Dissolved Air Flotation treatment package.





- Disinfection System– TM6
  - Gas Chlorine injection and Chlorine Contact Time
    - Disinfection
      - Gas chlorine, bulk hypochlorite, and onsite hypochlorite generation alternatives
      - Most alternatives require new building
    - Chlorine Contact
      - CCB size and BE limit flow through the WTP
      - Alternatives include reuse of existing, new larger replacement CCB, and new supplemental CCB
      - High priority item and construction sequencing must be considered to ensure distribution system supply





Disinfection System – TM6
 Gas Chlorine injection and Chlorine Contact Time











#### • Disinfection System– TM6

Gas Chlorine injection and Chlorine Contact Time



\* Proposed CCB modifications.





\* Proposed new CCB.



#### Backwash System – TM7

- Filter Backwash System
  - Alternatives include continued municipal sewer discharge, Lake Whatcom discharge, and recycle
    - Below and above grade options
  - Status Quo
    - Expensive, cumbersome for high demand
  - Lake Whatcom
    - Significant monitoring and permitting requirements
    - Additional chemical addition systems likely
  - Recycle
    - Moderate monitoring and permitting requirements
  - Reuse of existing CCB possible in any scenario
    - Depends heavily on desired use of existing CCB





- Backwash System TM7
  - Filter Backwash System





- Structural & Architectural Components TM8
  - WTP Main Building and FWP Building
    - WTP Main Building
      - No major structural deficiencies, some corrosion of nonstructural components (MCC's, supports, piping, etc.)
      - Lacks space and access to equipment, non-compliant safety shower and eye-wash, security should be improved
      - Alternatives included expansion "up" and "out"
    - Finished Water Pump Building
      - Two structural deficiencies identified. Additional seismic bracing recommended
      - Lacks space and access for some equipment
      - No alternatives analyzed





Structural & Architectural Components – TM8
 WTP Main Building and FWP Building







## Risk Assessment Summary

- Risk Assessment TM9
  - Quantitative assessment of risk of failure
  - Scoring based on numerical scale of likelihood for failure and severity if failure occurs
    - Score = Likelihood (1-5) \* Severity (1-5)
  - Treatment processes broken down into components
    - Raw water intake,
    - Raw water pumps,
    - Raw water instrumentation,



• Etc.



#### **Risk Assessment Summary**

#### Risk Assessment

Component	Impact(s)	Confined Space or Health & Safety Hazard?	Likelihood	Severity	Combined Score	Rank
Raw water intake	Loss of production, no service.	Y	2	2	4	13
Raw water pumps	Loss of production, no service.	Y	3	3	9	6
Raw water	DOH non-compliance,	Ν	2	1	2	16
instrumentation	regulatory action					
Alum delivery	Decrease in water quality,	Y	4	4	16	1
system	increase in maintenance					
Flocculation tank	DOH non-compliance, decrease	N	2	3	6	9
	in water quality, increase in					
	maintenance					





## **Risk Assessment Summary**

Risk Assessment

High Risk	Moderate Risk	Low Risk	Minimal Risk
Alum delivery system	Raw water pumps	Raw water intake	Raw water instrumentation
Chlorine contact basin	Clearwell transfer pumps	Filters 1 & 2	Clearwell
	Cl Disinfection system	Filters 3 & 4	Finished water instrumentation
	Soda Ash delivery system		WTP Main Bldg. piping
	Finished water pumps		WTP FWP Bldg. piping
	Flocculation tank		WTP Main Bldg. electrical
	WTP SCADA		WTP FWP Bldg. electrical
	WTP Security		





- Introduction
- Description of Existing Facilities
- Background and Project History
  - Technical memorandum summary
  - Risk assessment summary
- WTP Modification Alternatives
  - Minimum
  - Baseline
  - Maximum
  - Summary and Recommendations





#### Short Term Improvements (<10 years)

- Replace finished water pumps
- Replace transfer pumps
- Replace raw water pumps
- WTP Main Building seismic retrofits
- Finished Water Pump Building seismic retrofits
- Chlorine gas modifications
- WTP Security improvements

#### Long Term Improvements

#### (>10 years)

- Chemical addition system
   improvements
- New 0.3 MG CCB
- Rehabilitate existing filters
- Rehabilitate existing CCB
- Backwash recycle implementation





#### Short Term Improvements (<10 years)

- Replace finished water pumps
- Replace transfer pumps
- Replace raw water pumps
- WTP Main Building seismic retrofits
- Finished Water Pump Building seismic retrofits
- Chlorine gas modifications
- WTP Security improvements

#### **Long Term Improvements**

#### (>10 years)

- Chemical addition system
   improvements
- New 0.3 MG CCB
- Rehabilitate existing filters
- Rehabilitate existing CCB
- Backwash recycle implementation





#### • Baseline Alternative

- Short Term Improvements
  - Finished Water Pump Replacement
    - Pumping capacity & growth analysis
    - Replace all 4 finished water pumps
    - Replace all associated MCC equipment
    - Upgrade to VFD controls
  - Budget Cost
    - \$455,000
  - Other Considerations
    - DS supply during construction



#### • Baseline Alternative

- Short Term Improvements
  - Clearwell Transfer Pump Replacement
    - Replace both clearwell transfer pumps
    - Replace all associated MCC equipment
    - Upgrade to VFD controls
  - Budget Cost
    - \$210,000
  - Other Considerations
    - Separate electrical room?





- Baseline Alternative
  - Short Term Improvements
    - Raw Water Pump Replacement
      - Replace both raw water pumps
      - Replace all associated MCC equipment
    - Budget Cost
      - \$150,000
    - Other Considerations
      - Separate electrical room?





- Baseline Alternative
  - Short Term Improvements
    - WTP Main Building seismic retrofits
      - Non-structural bracing recommendations
    - Budget Cost
      - \$75,000
    - Other Considerations
      - Reorganization of existing space
      - Installation of new/upgraded components





#### • Baseline Alternative

- Short Term Improvements
  - WTP Finished Water Pump Building seismic retrofits
    - Structural diaphragm and roofing modifications
    - Non-structural bracing recommendations
  - Budget Cost
    - \$180,000
  - Other Considerations
    - Installation of new/upgraded components





#### • Baseline Alternative

- Short Term Improvements
  - WTP security improvements
    - CCB security
    - Fencing and access control
    - Video monitoring
  - Budget Cost
    - \$75,000
  - Other Considerations
    - SVCA, park and delivery vehicle access
    - New CCB or buildings?





Short Term Improvements	Cost
Replace finished water pumps	• \$455,000
<ul> <li>Replace transfer pumps</li> </ul>	• \$210,000
<ul> <li>Replace raw water pumps</li> </ul>	• \$150,000
<ul> <li>WTP Main Building seismic retrofits</li> </ul>	• \$75,000
<ul> <li>Finished Water Pump Building seismic retrofits</li> </ul>	• \$180,000
<ul> <li>Chlorine gas modifications</li> </ul>	• \$153,000
<ul> <li>WTP Security improvements</li> </ul>	• \$75,000
<u>Contingency, Tax, Project Administration</u>	• <u>\$1,277,000</u>
TOTAL	\$2,575,000



#### Short Term Improvements (<10 years)

- Replace finished water pumps
- Replace transfer pumps
- Replace raw water pumps
- WTP Main Building seismic retrofits
- Finished Water Pump Building seismic retrofits
- Chlorine gas modifications
- WTP Security improvements

#### Long Term Improvements

#### (>10 years)

- Chemical addition system
   improvements
- New 0.3 MG CCB
- Rehabilitate existing filters
- Rehabilitate existing CCB
- Backwash recycle implementation





#### Short Term Improvements (<10 years)

- Replace finished water pumps
- Replace transfer pumps
- Replace raw water pumps
- WTP Main Building seismic retrofits
- Finished Water Pump Building seismic retrofits
- Chlorine gas modifications
- WTP Security improvements

#### **Long Term Improvements**

#### (>10 years)

- Chemical addition system improvements
- New 0.3 MG CCB
- Rehabilitate existing filters
- Rehabilitate existing CCB
- Backwash recycle implementation





#### • Baseline Alternative

- Long Term Improvements
  - Chemical Addition System Improvements
    - Replace alum tank and metering pumps
    - Replace soda ash tank and metering pumps
    - Relocate chemicals to new, standalone building
  - Budget Cost
    - \$2,110,000
  - Other Considerations
    - DS supply during construction





- Baseline Alternative
  - Long Term Improvements
    - New 0.3 MG chlorine contact basin
      - Replaces existing CCB
      - Provide maximum access and treatment flexibility
    - Budget Cost
      - \$990,000
    - Other Considerations
      - DS supply during construction





#### • Baseline Alternative

- Long Term Improvements
  - Rehabilitate existing filters
    - Empty and inspect filters
    - Rehabilitate underdrain, piping, coatings, wash system
    - Refill with new, fresh media
  - Budget Cost
    - \$100,000
  - Other Considerations
    - DS supply during construction
    - Perform during low-demand, winter months





- Baseline Alternative
  - Long Term Improvements
    - Rehabilitate existing CCB
      - Provide seal welding, new coatings, new appurtenances
      - Install seismic retrofits and new controls
    - Budget Cost
      - \$620,000
    - Other Considerations
      - Containment and environmental considerations





#### • Baseline Alternative

- Long Term Improvements
  - Backwash recycle implementation
    - Repurpose CCB for backwash recycle
    - Install new controls, appurtenances and piping
    - Modify existing piping connections and WQ monitoring
  - Budget Cost
    - \$630,000
  - Other Considerations
    - Permitting and DOH approval
    - Potential decrease in finished water quality





Long Term Improvements	Cost
<ul> <li>Chemical addition system improvements</li> </ul>	• \$2,110,000
<ul> <li>New 3.0 MG welded steel CCB</li> </ul>	• \$990,000
<ul> <li>Rehabilitate existing filters</li> </ul>	• \$100,000
<ul> <li>Rehabilitate/repurpose existing CCB</li> </ul>	• \$620,000
<ul> <li>Implement backwash recycle improvements</li> </ul>	• \$630,000
Contingency, Tax, Project Administration	• <u>\$4,378,000</u>
TOTAL	\$8.828.000



































#### Next Steps

- Prepare Draft Alternatives Analysis Report
- District & Staff Input Meeting
  - July 21, 2021 @ 300PM
- Board Informational Presentation
  - August 11, 2021 @ 630PM
- Board Input Meeting and Discussion
  - August 25, 2021 @ 800AM
- Modify and Finalize Alternatives Analysis Report





#### Questions?



